

FIG. 1




FIG. 2




FIG. 3




FIG. 4





FIG. 5



Variant handling

FIG. 6

D:\SAS Homepage\home(V2.0).HTM-Microsoft Internet Explorer

Address

---

TSID

Full Report  
☐

Small Report  
☐

German

Welcome to the  
Service Assistance System (SAS)

---

TSID: 1-2P21EM

Date/Time: 2/1/03, 9:14:04 p.m. CET

Vehicle data:

VIN WDB211086ABCDEF12

Mileage: 123 456 km

Vehicle condition:

ESP information light.....flashing

High beam driver's side.....defective

Motor oil level.....minimum reached

Defects found:

ESP (electric stability program)

C0815.....Rpm sensor interrupted

C4711.....Steering angle sensor  
not initialized

SRS (airbag)

B1234.....Line to belt lock front left  
has short circuit to ground

B9876.....Coding for side airbag rear  
not correct

FIG. 7




FIG. 8